

LE TSO 1845.6
 LE CSO 1155
 LE TSN 7,804.0
 LE CSN 6,832
 LP TSO 355.9

N1SP
 S/N BC-42
 HOBBS 4446.9
 ACTT 14446.9
 LG CYC 10,197

RE TSO 1845.6
 RE CSO 1155
 RT TSN 12,531.7
 RE CSN 11,615
 RP TSO 355.9

Beech Model A200 Series BC-1 THRU BC-75 Beech Maintenance Manual P/N 101-590010-19B12 Rev. 28 April 2006 and Beech Maintenance Manual P/N 92-37443-1B/-2B dated 30 April 2002 Inspection Requirements, Component Overhaul & Replacement Schedule							
							(For Reference Only)
Componet	P/N	S/N	Limits Hours	Limits Cycles	Limits Days	Hours and/or Date Completed	Hours and/or Date Next Due
Chapter 5-00-00 Inspection Requirements Maint Manual P/N 101-590010-19B12							
Inspection Program - Phase 1 thru 4			800			14,446.9	15,246.9
Inspection Program - Phase 1 thru 4					2 Yr.	Mar-08	Mar-10
Next Phase Due	Phase 1		200			14,446.9	14,646.9
Next Phase Due	Phase 1				1 Yr.	Mar-08	Mar-09
Aircraft Weight Check (FAR Part 135 Requirement)					3 Yr.	Sep-06	Sep-09
Chapter 12-20-00 Lubrication Requirements Maint Manual P/N 101-590010-19B12							
200 Hr Lube			200			14,446.9	14,646.9
400 Hr Lube			400			14,446.9	14,846.9
600 Hr Lube			600			14,446.9	15,046.9
800 Hr Lube			800			14,446.9	15,246.9
1200 Hr Lube			1,200			13,587.6	14,787.6
Wing Bolt Lube					1 Yr.	Mar-08	Mar-09
Miscellaneous Airframe Chapter 5-11-00 Overhaul & Replacement Schedule Maint Manual P/N 101-590010-19B12							
Pneumatic Flow Control Unit Valve Filter (clean)	1520173		800			14,446.9	15,246.9
ELT Battery Due Date						May-07	Jul-09
ELT Inspection [FAR 91.207(d)]					1 Yr.	Mar-08	Mar-09
Miscellaneous Airframe Chapter 5-20-00 Special Inspections Maint Manual P/N 101-590010-19B12							
Pilots Altimeter & Static System	066-03064-0005	29877			2 Yr.	Mar-08	Mar-10
Co-Pilots Altimeter & Static System	570-23932-106	945			2 Yr.	Mar-08	Mar-10
#1 Transponder	011-004900-00	83706785			2 Yr.	Mar-08	Mar-10
Fwd Oxygen Shut-Off Valve Inspection					2 Yr.	Mar-08	Mar-10
Aft Oxygen Shut-Off Valve Inspection					2 Yr.	Mar-08	Mar-10
Pedestal Power Lever Pin Inspection			1,200			14,214.3	15,414.3
Edge Lighted Panels Inspection			2,000			13,997.5	15,997.5
Edge Lighted Panels Inspection					4 Yr.	Jun-06	Jun-10

LE TSO 1845.6
LE CSO 1155
LE TSN 7,804.0
LE CSN 6,832
LP TSO 355.9

N1SP
S/N BC-42
HOBBS 4446.9
ACTT 14446.9
LG CYC 10,197

RE TSO 1845.6
RE CSO 1155
RT TSN 12,531.7
RE CSN 11,615
RP TSO 355.9

Beech Model A200 Series BC-1 THRU BC-75

**Beech Maintenance Manual P/N 101-590010-19B12 Rev. 28 April 2006 and
Beech Maintenance Manual P/N 92-37443-1B/-2B dated 30 April 2002**

Inspection Requirements, Component Overhaul & Replacement Schedule

(For Reference Only)

Componet	P/N	S/N	Limits Hours	Limits Cycles	Limits Days	Hours and/or Date Completed	Hours and/or Date Next Due
Utility Systems - Chapter 04-30-02							
Airworthiness Limitations Section							
Maint Manual P/N 92-37443-1B/-2B							
LH Eng Fire Bottle Hydrostatic Test	4DS-700	07782B2			5 Yr.	May-07	May-12
LH Eng Fire Bottle Squibb Cartridge (Service)	M13082-5	11415			4 Yr.	Jan-05	Jan-09
LH Eng Fire Bottle Squibb Cartridge (Total)	"	"			6 Yr.	Jul-04	Jul-10
RH Eng Fire Bottle Hydrostatic Test	4DS-700	A2392			5 Yr.	May-07	May-12
RH Eng Fire Bottle Squibb Cartridge (Service)	M13082-5	12246			4 Yr.	Aug-05	Aug-09
RH Eng Fire Bottle Squibb Cartridge (Total)	"	"			6 Yr.	Jul-04	Jul-10
Cockpit Fire Bottle Hydrostatic Test	4B240ET-1	V-460776			12 Yr.	May-07	May-19
Cabin Fire Bottle Hydrostatic Test	4B240ET-1	V-526030			12 Yr.	May-07	May-19
O2 Bottle Hydrostatic Test	DOT-3HT-1850	812961			3 Yr.	Apr-08	Apr-11
Oxygen Bottle Service Life	"	"			24 Yr.	Feb-05	Feb-29
Oxygen Bottle Service Life	"	"		4,380		0	4,380
Oxygen Bottle Regulator Overhaul	172070	5795	on condition		H53	#VALUE!	
Landing Gear - Chapter 5-20-00							
Special Inspections							
Maint Manual P/N 101-590010-19B12							
NLG Actuator Clevis Insp.	50-820208-5	ALG-4101		1,000		10,197	11,197
LH MLG Actuator Clevis Insp.	99-810057-652	ALG-10734		1,000		10,197	11,197
RH MLG Actuator Clevis Insp.	99-810057-651	ALG-10732		1,000		10,197	11,197
NLG Actuator End-Play Insp.	50-820208-5	ALG-4101		1,000		9,984	10,984
NLG Actuator End-Play Insp.	"	"			30 Mos.	May-07	Nov-09
LH MLG Actuator End-Play Insp.	99-810057-652	ALG-10734		1,000		10,197	11,197
LH MLG Actuator End-Play Insp.	"	"			30 Mos.	Mar-08	Sep-10
RH MLG Actuator End-Play Insp.	99-810057-651	ALG-10732		1,000		10,197	11,197
RH MLG Actuator End-Play Insp.	"	"			30 Mos.	Mar-08	Sep-10
NLG Shock Absorber, Drag Bracc, Axle and Torque Knee Assemblies				8,000		9,258	17,258
NLG Shock Absorber, Drag Brace, Axle and Torque Knee Assemblies					6 Yr.	Sep-03	Sep-09
LH MLG Shock Absorber, Drag Brace, Axle and Torque Knee Assemblies				8,000		9,533	17,533
LH MLG Shock Absorber, Drag Brace, Axle and Torque Knee Assemblies					6 Yr.	Jan-05	Jan-11
RH MLG Shock Absorber, Drag Brace, Axle and Torque Knee Assemblies				8,000		9,533	17,533
RH MLG Shock Absorber, Drag Brace, Axle and Torque Knee Assemblies					6 Yr.	Jan-05	Jan-11
Landing Gear Retract Gearbox & Clutch Inspection	613	961-A-77		8,000		9,533	17,533
Landing Gear Retract Gearbox & Clutch Inspection	"	"			6 Yr.	Jan-05	Jan-11
Nose Wheel Inspection					1 Yr.	Mar-08	Mar-09
Nose Wheel Inspection			450			14,446.9	14,896.9
LH Main IB Wheel Inspection (Ref. CMM)	101-8001-47	5125	each tire change			14,298.6	next tire change
LH Main OB Wheel Inspection (Ref. CMM)	101-8001-47	K9525	each tire change			14,298.6	next tire change
RH Main IB Wheel Inspection (Ref. CMM)	101-8001-47	7614	each tire change			14,453.9	next tire change
RH Main OB Wheel Inspection (Ref. CMM)	101-8001-47	3221	each tire change			14,453.9	next tire change

LE TSO 1845.6
 LE CSO 1155
 LE TSN 7,804.0
 LE CSN 6,832
 LP TSO 355.9

N1SP
 S/N BC-42
 HOBBS 4446.9
 ACTT 14446.9
 LG CYC 10,197

RE TSO 1845.6
 RE CSO 1155
 RT TSN 12,531.7
 RE CSN 11,615
 RP TSO 355.9

Beech Model A200 Series BC-1 THRU BC-75

**Beech Maintenance Manual P/N 101-590010-19B12 Rev. 28 April 2006 and
 Beech Maintenance Manual P/N 92-37443-1B/-2B dated 30 April 2002**

Inspection Requirements, Component Overhaul & Replacement Schedule

(For Reference Only)

Componet	P/N	S/N	Limits Hours	Limits Cycles	Limits Days	Hours and/or Date Completed	Hours and/or Date Next Due
Landing Gear - Chapter 5-11-00 Overhaul & Replacement Schedule Maint Manual P/N 101-590010-19B12							
Landing Gear/Brake Hoses (in Wheel Well)					5 Yr.	Oct-08	Oct-13
Landing Gear Retract Motor Overhaul					6 Yr.	Jan-05	Jan-11
Landing Gear Retract Motor Overhaul				8,000		9,533	17,533
NLG Actuator Overhaul	50-820208-5	ALG-4101			6 Yr.	Jan-05	Jan-11
NLG Actuator Overhaul	"	"		8,000		9,533	17,533
LH MLG Actuator Overhaul	99-810057-652	ALG-10734			6 Yr.	Mar-08	Mar-14
LH MLG Actuator Overhaul	"	"		8,000		10,197	18,197
RH MLG Actuator Overhaul	99-810057-651	ALG-10732			6 Yr.	Mar-08	Mar-14
RH MLG Actuator Overhaul	"	"		8,000		10,197	18,197
LH IB MLG Brake Assy. Overhaul (Ref. CMM)	101-8001-9	D1020				14,446.9	OC
LH MLG OB Brake Assy. Overhaul (Ref. CMM)	101-8001-9	F2365				14,446.9	OC
RH MLG IB Brake Assy. Overhaul (Ref. CMM)	101-8001-9	E2194				13,449.7	OC
RH MLG OB Brake Assy. Overhaul (Ref. CMM)	101-8001-9	D1114				13,449.7	OC
Wings - Chapter 5-20-00 Special Inspections Maint Manual P/N 101-590010-19B12							
LH Nacelle Fuel Probe Contamination Inspection			2,400			14,214.3	16,614.3
LH Nacelle Fuel Probe Contamination Inspection					30 Mos.	May-07	Nov-09
RH Nacelle Fuel Probe Contamination Inspection			2,400			14,214.3	16,614.3
RH Nacelle Fuel Probe Contamination Inspection					30 Mos.	May-07	Nov-09
LH Flap Flexible Shaft Inspection				5,000		5,000	10,000
RH Flap Flexible Shaft Inspection				5,000		5,000	10,000
Wings - Structural Repair Manual P/N 98-39006C, Dated Oct 2005							
LH Outboard Wing Panel Up & Lwr Fwd Spar Cap Insp.					1 Yr.	Mar-08	Mar-09
LH Wing Attach Fitting Insp. (Fluorescent Penetrant)					5 Yr.	Oct-08	Oct-13
RH Outboard Wing Panel Up & Lwr Fwd Spar Cap Insp.					1 Yr.	Mar-08	Mar-09
RH Wing Attach Fitting Insp. (Fluorescent Penetrant)					5 Yr.	Oct-08	Oct-13
Wings - Chapter 4-20-02 Airworthiness Limitations Section Maint Manual P/N 92-37443-1B/-2B							
LH Lower Forward Fitting Counterbores & Barrel Nut holes (Eddy Current)			First 20,000 every 1,200			0.0	20,000
RH Lower Forward Fitting Counterbores & Barrel Nut holes (Eddy Current)			First 20,000 every 1,200			0.0	20,000

LE TSO 1845.6
 LE CSO 1155
 LE TSN 7,804.0
 LE CSN 6,832
 LP TSO 355.9

N1SP
 S/N BC-42
 HOBBS 4446.9
 ACTT 14446.9
 LG CYC 10,197

RE TSO 1845.6
 RE CSO 1155
 RT TSN 12,531.7
 RE CSN 11,615
 RP TSO 355.9

Beech Model A200 Series BC-1 THRU BC-75							
Beech Maintenance Manual P/N 101-590010-19B12 Rev. 28 April 2006 and							
Beech Maintenance Manual P/N 92-37443-1B/-2B dated 30 April 2002							
Inspection Requirements, Component Overhaul & Replacement Schedule						(For Reference Only)	
Componet	P/N	S/N	Limits Hours	Limits Cycles	Limits Days	Hours and/or Date Completed	Hours and/or Date Next Due
Wings - Chapter 4-20-04							
Airworthiness Limitations Section							
Maint Manual P/N 92-37443-1B/-2B							
LH Wing Bolt Penetrant Insp. (Upr Fwd, Upr Aft, and Lwr Aft)					5 Yr.	Oct-08	Oct-13
LH Wing Bolt & Nut Change (Upr Fwd, Upr Aft, and Lwr Aft) (Inconel)					15 Yr.	Sep-03	Sep-18
LH Wing Bolt & Nut Change (Upr Fwd, Upr Aft, and Lwr Aft) (Inconel)			15,000			13,335.2	28,335.2
LH Wing Bolt & Nut Change (Lwr Fwd)					5 Yr.	Oct-08	Oct-13
RH Wing Bolt Penetrant Insp. (Upr Fwd, Upr Aft, and Lwr Aft)					5 Yr.	Oct-08	Oct-13
RH Wing Bolt & Nut Change (Upr Fwd, Upr Aft, and Lwr Aft) (Inconel)					15 Yr.	Sep-03	Sep-18
RH Wing Bolt & Nut Change (Upr Fwd, Upr Aft, and Lwr Aft) (Inconel)			15,000			13,335.2	28,335.2
RH Wing Bolt & Nut Change (Lwr Fwd)					5 Yr.	Oct-08	Oct-13
Wings							
Aircraft Flight Manual							
Revised Aug 1997							
Wing and Associated Structure Fatigue Safelife			20,000			0.0	20,000.0
Structural Integrity							
Continuous Inspection Procedures							
Manual P/N 98-36783M							
dated 31 Oct 1997							
Chart 1							
Airstair Door, Escape Hatch & Assoc. Struct.			1,200			13,587.6	14,787.6
Fwd. Pressure Bulkhead Insp.			3,000			12,033.5	15,033.5
Windshield Upr & Lwr Corners and Sill Inspection			1,200			13,587.6	14,787.6
Cabin Door Frame Inspection at all four Corners and upper Latch hook catches			1,200			13,587.6	14,787.6
Exterior Skin Insp. (including nose wheel well keels)			1,200			13,587.6	14,787.6
Fuselage Frame Inspection FS 84 thru FS 347.75 (under floor)			1,200			13,587.6	14,787.6
Fuselage Web Frame Inspection FS 179 thru FS 271			First - 15,000			0.0	15,000.0
Inspection of Stringers 7,8,9 & 10 at FS 88 thru FS 125 and instrument panel Support Bracket			12,000			10,490.4	22,490.4
Flight Control Pulley Brackets and Castings			6,000			10,490.4	16,490.4
Aft. Side of Aft. Pressure Bulkhead			600			14,214.3	14,814.3
Chart 2							
Fuselage Stringer Insp. on non-reworked stringers 5-11, Refer to figures 2 & 3 and AD93-25-07 sprs by AD 50-01-18.			600			14,214.3	14,814.3
Inspection above & below stringer cutouts, Refer to Figure 4, Fwd. Side of Aft Press Bulkhead.			3,000			13,587.6	16,587.6

LE TSO 1845.6
 LE CSO 1155
 LE TSN 7,804.0
 LE CSN 6,832
 LP TSO 355.9

N1SP
 S/N BC-42
 HOBBS 4446.9
 ACTT 14446.9
 LG CYC 10,197

RE TSO 1845.6
 RE CSO 1155
 RT TSN 12,531.7
 RE CSN 11,615
 RP TSO 355.9

Beech Model A200 Series BC-1 THRU BC-75

Beech Maintenance Manual P/N 101-590010-19B12 Rev. 28 April 2006 and

Beech Maintenance Manual P/N 92-37443-1B/2B dated 30 April 2002

Inspection Requirements, Component Overhaul & Replacement Schedule

(For Reference Only)

Componet	P/N	S/N	Limits Hours	Limits Cycles	Limits Days	Hours and/or Date Completed	Hours and/or Date Next Due
Fuselage							
Aircraft Flight Manual							
Revised Aug 1997							
Replace Windshield Frame Screws				12,000		11,341.6	23,341.6
Replace Cabin Airstair Door Fwd & Aft Side Latches				6,000		10,000.0	16,000.0
Replace Cabin Airstair Door Upper Door Hook Mechanism				12,000		10,000.0	22,000.0
Engine Overhaul & Hot Section							
Inspection Frequency							
P&WC S.B. 3003R20 dated 7/16/02							
LH Eng - Overhaul ETT @ OH = 5,958.4, ETC @ OH = 5,677	PT6A-41	PCE 85247	3,000			12,601.3	15,601.3
LH Eng - HSI	"	"	1,500			14,091.0	15,591.0
LH Eng - HP Fuel Pump	025323-300-03	8362	3,500			12,601.3	16,101.3
LH Engine-FCU	3244755-16-14	A45074	3,500			12,601.3	16,101.3
LH Engine Vibration Isolator Mounts			4,000			12,601.3	16,601.3
LH Engine Flammable Fluid Carrying Hoses					5 Yr	Jun-06	Jun-11
LH Starter/Generator	23048-016	6605	1,000			14,446.9	15,446.9
LH Starter/Generator QAD Attach Flange Insp.			Whenever Starter/Generator Is Removed			14,446.9	15,446.9
Engine Inspection							
P&W Maint. Manual P/N 3021442							
Rev 39 dated 04/28/06							
LH Eng. Fuel Nozzle Flow Check			400			14,446.9	14,846.9
LH Engine Compressor Wash			400			14,446.9	14,846.9
LH Eng. Oil Filter Change			1,000			14,446.9	15,446.9
LH Eng. P3 Air Filter Change			1,000			14,446.9	15,446.9
RH Eng. Fuel Nozzle Flow Check			400			14,446.9	14,846.9
RH Engine Compressor Wash			400			14,446.9	14,846.9
RH Eng. Oil Filter Change			1,000			14,446.9	15,556.9
RH Eng. P3 Air Filter Change			1,000			14,446.9	15,446.9

LE TSO 1845.6
 LE CSO 1155
 LE TSN 7,804.0
 LE CSN 6,832
 LP TSO 355.9

N1SP
 S/N BC-42
 HOBBS 4446.9
 ACTT 14446.9
 LG CYC 10,197

RE TSO 1845.6
 RE CSO 1155
 RT TSN 12,531.7
 RE CSN 11,615
 RP TSO 355.9

**Beech Model A200 Series BC-1 THRU BC-75
 Beech Maintenance Manual P/N 101-590010-19B12 Rev. 28 April 2006 and
 Beech Maintenance Manual P/N 92-37443-1B/-2B dated 30 April 2002
 Inspection Requirements, Component Overhaul & Replacement Schedule**

Componet	P/N	S/N	Limits Hours	Limits Cycles	Limits Days	(For Reference Only)	
						Hours and/or Date Completed	Hours and/or Date Next Due
Engine Rotor Components Service Life Times P&WC S.B. 3002R24 dated 09/10/02							
LH Hub, Compressor (1 st Stage)	3021911	8H183		20,000		0	20,000
LH Disk, Compressor (2 nd Stage)	3023112	A00072B8		20,000		5,677	25,677
LH Disk, Compressor (3 rd Stage)	3023113	A0002DKY		20,000		5,677	25,677
LH Impeller, Centrifugal	3017463	1B304		20,000		0	20,000
LH Disk, Compressor Turbine	3049291-01	A00080MO		10,000		5,677	15,677
LH Disk, Power Turbine (1 st Stage)	3029312	A0002WBN		30,000		5,677	35,677
LH Disk, Power Turbine (2 nd Stage)	3029313	A00038DA		30,000		5,677	35,677
RH Hub, Compressor (1 st Stage)	3021911	2F441		20,000		0	20,000
RH Disk, Compressor (2 nd Stage)	3023112	A0002D		20,000		10,460	30,460
RH Disk, Compressor (3 rd Stage)(1,528 cyc @ O/H)	3023113	29A515		20,000		8,932	28,932
RH Impeller, Centrifugal	3036793	58B711		20,000		10,460	30,460
RH Disk, Compressor Turbine	3049291-01	A0072C7		10,000		10,460	20,460
RH Disk, Power Turbine (1 st Stage)(4,432 cyc @ O/H)	3029312	2X569		30,000		6,028	36,028
RH Disk, Power Turbine (2 nd Stage)(4,432 cyc @ O/H)	3029313	3X211		30,000		6,028	36,028
Propeller Overhaul Hartzell Service Letter HC-SL-61-61 rev Y dated 04/01/04							
LH Propeller (PTT = 11,766.1)	HC-B3TN-3G	BUA23030	3,000			13,000.5	16,000.5
LH Propeller	"	"			5 Yr.	Nov-06	Nov-11
RH Propeller (PTT = 7,072.6)	HC-B3TN-3G	BUA24922	3,000			13,104.3	16,104.3
RH Propeller	"	"			5 Yr.	Nov-06	Nov-11
Propeller Governor Overhaul Woodward Service Bulletin No. 33580L dated 12/10/02							
LH Prop Governor (Unit TSO 847.7 when installed)	8210-007	1744423	4,500			11,608.4	15,760.7
LH Over Speed Governor	210638	1587774	6,500			10,995.7	17,495.7
RH Prop Governor	8210-007G	1991360G	4,500			12,601.3	17,101.3
RH Over Speed Governor	210638	2122207	6,500			11,615.6	18,115.6

LE TSO 1845.6
 LE CSO 1155
 LE TSN 7,804.0
 LE CSN 6,832
 LP TSO 355.9

N1SP
 S/N BC-42
 HOBBS 4446.9
 ACTT 14446.9
 LG CYC 10,197

RE TSO 1845.6
 RE CSO 1155
 RT TSN 12,531.7
 RE CSN 11,615
 RP TSO 355.9

**Beech Model A200 Series BC-1 THRU BC-75
 Beech Maintenance Manual P/N 101-590010-19B12 Rev. 28 April 2006 and
 Beech Maintenance Manual P/N 92-37443-1B/-2B dated 30 April 2002
 Inspection Requirements, Component Overhaul & Replacement Schedule**

(For Reference Only)

Componet	P/N	S/N	Limits Hours	Limits Cycles	Limits Days	Hours and/or Date Completed	Hours and/or Date Next Due
Instructions For Continued Airworthiness contained in FAA Forms 337:							
Argus S000 Moving Map Display - See Form 337 dated 02/18/99			Phase 1 and 3	or 12 months		Mar-08	Mar-09
Universal Avionics UNS-1LFMS Mgt Sys - See Form 337 dated 06/24/02			Phase 1 and 3	or 12 months		Mar-08	Mar-09
Sandel Avionics LLC SN3500 Nav Dis Sys - See Form 337 dated 06/24/02			Phase 1 and 3	or 12 months		Mar-08	Mar-09
Primus 660 Weather Radar W/Universal MFD640 - See Form 337 dated 06/24/02			Phase 1 and 3	or 12 months		Mar-08	Mar-09
Air Cell Telephone AGT.02 - See Form 337 dated 06/24/02			Phase 1 and 3	or 12 months		Mar-08	Mar-09
Northern Airborne AA95 Audio - See Form 337 dated 06/24/02			Phase 1 and 3	or 12 months		Mar-08	Mar-09
Collins Proline II Nav - See Form 337 dated 06/24/02			Phase 1 and 3	or 12 months		Mar-08	Mar-09
Collins Proline I Comm - See Form 337 dated 06/24/02			Phase 1 and 3	or 12 months		Mar-08	Mar-09
Collins Proline II DME - See Form 337 dated 06/24/02			Phase 1 and 3	or 12 months		Mar-08	Mar-09
Kenwood Cassette/CD - See Form 337 dated 06/24/02			Phase 1 and 3	or 12 months		Mar-08	Mar-09
Ryan TCAD 9900BX - See Form 337 dated 03/29/03			Phase 1 and 3	or 12 months		Mar-08	Mar-09
Ryan TCAD 9900DX (Ramp Test Only) - See Form 337 dated 03/29/03			every 24 mnth			Mar-08	Mar-09
Goodrich Avionics PS-835 Emer Pwr - See Form 337 dated 03/29/03			Phase 1 and 3	or 12 months		Mar-08	Mar-09
Goodrich Avionics PS-835 Emer Pwr Capacity Tst - See Form 337 dated 03/29/03			every 12mnth			Mar-08	Mar-09
Goodrich Avionics PS-835 Emer Pwr Periodic - See Form 337 dated 03/29/03			every 6 mnth			Mar-08	Mar-09
Universal Avionics TAWS - See Form 337 dated 06/13/03			Phase 1 and 3	or 12 months		Mar-08	Mar-09
Concorde Battery Capacity Test - See Form 337 dated 05/09/05			1 yr or 600 hr evry 3 months	or 200 hr		Mar-08 14446.9 Mar-08	Mar-09 15046.9 Mar-09